

JUN 27 2016

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENTOIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emr.state.nm.us/ocd/DistrictIII/3district.htm>

## BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test May 20, 2016 Operator DJ Simmons API #30-0 39-22882

Property Name Hanson Federal Well No. 2 Location: Unit N Section 3 Township 23N Range 7W

Pressure (Shut-In or Producing) Producing Tubing 105 Intermediate N/A Casing 108 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

## PRESSURES:

TESTING TIME	BRADENHEAD			INTERMEDIATE	
	BH	INT	CSG	INT	CSG
5 minutes	0		108		
10 minutes	0		108		
15 minutes	0		108		
20 minutes					
25 minutes					
30 minutes					

## BRADENHEAD INTERMEDIATE

	FLOWED	FLOWED
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN \_\_\_\_\_ BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

## REMARKS:

Well producing plunger well, on its off cycle, nothing on Bradenhead.

By Dustin K. Johnson Witness \_\_\_\_\_

Lease Operator

(Position)