

Amoco Production Company

Cleanout / Plugback Report

Print Date
11/08/94

Well Name: LACKEY /B/ LS 12R

Well Number: R012L21

Job Start Date: 10/4/94

Work Activity Number: 223

Job End Date: 10/5/94

Primary Service Company Name: Aztec Well Service

Job Field Estimated Cost:

Cleanout/Plugback Type: Plugback

Cleanout/Plugback Method: Wireline

Plug Material Used: CIBP

Recovered Material:

Top Depth: 6,766 FT.

Bottom Depth: 6,767 FT.

Tubular/Hole I.D.: 3.830 IN.

Job Comments:

HALLIBURTON LOGGING SET CIBP AT 6766 DUMP 4 SX CMT ON TOP. RAN GUAGE RING AND TAG CCMT AT 6716. DAKOTA ABAND
PRESURE TESTED CASING WWATER AND 500 PSI F/SURFACE TO 6766 W/NO LEAK OFF. GOOD TEST.

