



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3
JUL 07 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-7-16 Operator Enwest API #30-0 39-23482
Property Name J. Cantaluba Well No. 396 8 Location: Unit 17 Section 17 Township 23 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 142 Intermediate N/A Casing 130 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>140</u>		
10 min	<u>0</u>		<u>144</u>		
15 min	<u>0</u>		<u>148</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>/</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Nothing when opened - Nothing when
opened after 5 min shut in

By Walter
Prod. Foreman
(Position)

Witness Monica Kuchling

E-mail address _____