



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUL 06 2016

Date of Test 7/6/2016 Operator Burlington API #30-0 39-06333

Property Name Jicarilla 153 Well No. 3 Location: Unit Section 26 Township 26 Range 5

Well Status (Shut-In or Producing) Initial PSI: Tubing 104 Intermediate NA Casing 104 Bradenhead 49

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0.4		104		
10 min	0.2		104		
15 min	0.2		105		
20 min	0.1		105		
25 min	0.1		106		
30 min	0.1		106		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 17 INTERMEDIATE NA

REMARKS:

BH through 1" valve, hard blow for 2 min 30 sec, moderate blow through 6 min,
blow through 15 min, steady light blow for rest of test. Gas samples already
collected

By [Signature] MSO.
(Position)

Witness [Signature] Kelly

E-mail address