



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUL 14 2016

Date of Test 7-14-16 Operator Concepcion API #30-0 39-22450
Property Name Lindholm 31st Well No. 7 Location: Unit 28 Section 28 Township 24 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 85 Intermediate 0 Casing 242 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	242	0	242
10 min	0	0	242	0	242
15 min	0	0	242	0	242
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: BH - nothing when opened - nothing when
opened after 5 min shut-in. Int - long puff to clear at 5 seconds.
But out on long partially covered swab

By Jerry Muen
(Position)

Witness Monica Kuchling
Int - nothing when opened after
5 min shut-in

E-mail address _____