



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JUL 20 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-20-16 Operator HPAC LLC API #30-0 43-20949
Property Name Eagle Springs & Feat Well No. 1H Location: Unit 3 Section 8 Township 19 Range 4
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 3 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>3</u>		
10 min	<u>0</u>		<u>3</u>		
15 min	<u>0</u>		<u>3</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>/</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Nothing when opened - Nothing when opened
after 5 min shut in.

By Lynn Halich
Pumper
(Position)

Witness Monica Tackling

E-mail address _____