



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

JUL 22 2016

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/15/2016 Operator Energen Resources API # 3003921166

Property Name JICARILLA 95 3A Location: Unit D Section 35 Township 27 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 90 Intermediate N/A Casing 99 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	<u>0</u>	<u>100</u>	<u>N/A</u>			Steady Flow	
10 minutes	<u>0</u>	<u>100</u>	<u>N/A</u>			Surges	
15 minutes	<u>0</u>	<u>101</u>	<u>N/A</u>			Down to Nothing	
20 minutes	<u>0</u>	<u>101</u>	<u>N/A</u>			No Flow	<input checked="" type="checkbox"/>
25 minutes	<u>0</u>	<u>101</u>	<u>N/A</u>			Gas	
30 minutes	<u>0</u>	<u>101</u>	<u>N/A</u>			Gas and Water	
5 minute SI	<u>0</u>	<u>102</u>	<u>N/A</u>			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By Jason Paul Witness _____
Field Foreman
(Position)