



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-27-2016 Operator Red Wolf Prod. API #30-039-05941

Property Name Hill Well No. 7 Location: Unit C Section 23 Township 25 Range 3

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 68 Intermediate NA Casing 68 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	-	NA	68		
10 min	-	↙	68		
15 min	-	↘	68		
20 min		↘			
25 min		↘			
30 min		↓			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
JUL 27 2016

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

Nothing on BH when opened. Opsi on BH after 5 min
Shut in. Nothing when opened after shut in.

By Bruce C Delattre

Witness [Signature] NMCD

(Position)

E-mail address _____