

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 258-1607
Facility Name: Huerfano 193	Facility Type: Gas Well

Surface Owner Federal	Mineral Owner Federal	API No. 3004520395
------------------------------	------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter J	Section 29	Township 26N	Range 09W	Feet from the 1790	North/South Line South	Feet from the 1650	East/West Line East	County San Juan
----------------------	-------------------	---------------------	------------------	---------------------------	-------------------------------	---------------------------	----------------------------	------------------------

Latitude 36.45673 Longitude -107.80803


NATURE OF RELEASE

Type of Release Historic Contamination	Volume of Release Unknown	Volume Recovered 0
Source of Release Possible old earthen or dehy pit	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 07/25/2016 @ 1:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A	OIL CONS. DIV DIST. 3 AUG 08 2016	

Describe Cause of Problem and Remedial Action Taken.*
While cleaning up a small spill in the cribbing area of the Huerfano Unit 193 with a hydrovac truck more contamination (and older) was found. Third-party environmental was on location to sample and direct placement of pot holes to help delineate the affected area. The excavation at end of today, is approximately 27 feet x 21 feet and up to 13 feet deep. The base is at what appears to be degraded sandstone, and is below NMOCD Action Levels at about 12-13 feet. The contamination is concentrated on the west end near the separator. The contamination is old with some liner mixed in. It may be the an old earthen or dehy pit.

Describe Area Affected and Cleanup Action Taken.*
ConocoPhillips will continue remediation efforts.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 8/12/2016	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: August 3, 2016 Phone: (505) 258-1607	NCS1620926898	

* Attach Additional Sheets If Necessary

Sample Area for BTEX, TPH, including (MRO/ORO)

①