



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

AUG 16 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-16-16 Operator Burlington Resources API #30-0 45-34776
Property Name Allison let Well No. 6N Location: Unit N Section 16 Township 32 Range 6
Well Status(Shut-In or Producing) Initial PSI: Tubing 214 Intermediate 0 Casing 223 Bradenhead 63

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0	0	223	0	223	Steady Flow	
10 min	0	0	223	0	223	Surges	
15 min	0	0	223	0	223	Down to Nothing	/
20 min	0	0	223	0	224	Nothing	
25 min	0	0	223	0	224	Gas	/
30 min	0	0	223	0	224	Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 5

INTERMEDIATE 0

REMARKS:

BH Medium flow - dead at 4 min - Int -
Medium flow - dead at 15 min - Nothing
when opened after 5 min shut-in

By Frank H. Smith

Witness Monica Fuchling

(Position)

E-mail address _____

Gas analysis - well bore
schematic