



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3ddistrict.htm](http://emnr.state.nm.us/ocd/District%20III/3ddistrict.htm)

OIL CONS. DIV DIST. 3
AUG 22 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-22-16 Operator Mervin DeG API #30-0 39-22-18
Property Name Canada Mesa Well No. 1E Location: Unit 24 Section 24 Township 24 Range 6
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 120 Intermediate 114 Casing 162 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>175</u>		
10 min	<u>0</u>		<u>180</u>		
15 min	<u>0</u>		<u>182</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>/</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 114

REMARKS:

Nothing when opened - Nothing when
opened after 5 min shut-in

By Fred Alarcon
(Position) Pumper

Witness Mervin Kuehling

E-mail address _____