



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

OIL CONS. DIV DIST. 3
AUG 22 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-22-16 Operator Merrion D'G API #30-0 39-2-30-57
Property Name Canada Mesa Corn Well No. 4E Location: Unit 10 Section 10 Township 74 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 178 Intermediate N/A Casing 200 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>200</u>		
10 min	<u>0</u>		<u>200</u>		
15 min	<u>0</u>		<u>200</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing ✓

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Nothing when opened. Nothing when
opened after 5 min shut in

By Frank Harmon

Witness Merrion D'G

(Position)

Pumper

E-mail address _____