



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 24 2016

Date of Test 6-15-16 Operator Roddy Production API # 30-039-21258

Property Name Chacon Jic Ap. D Well No. 4 Location: Unit P Section 9 Township 23 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 85 Intermediate NA Casing 7 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>7</u>		
10 min	<u>0</u>		<u>7</u>		
15 min	<u>0</u>		<u>7</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>1</u>
Nothing	
Gas	<u>1</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Could hear a small puff of gas when opened then nothing after 1 or 2 seconds. Note this well has a packer in the hole. That's why casing psi was so low.

By Tom J

Witness _____

(Position)

E-mail address _____