



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 24 2016

Date of Test 7-21-16 Operator Reddy Production API #30-0 39-21346

Property Name Chacon Jicarilla PL Well No. 6 Location: Unit E Section 16 Township 23 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 69 Intermediate NA Casing 74 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Bradenhead	INTERM	Int	Csg	
TIME						
5 min	<u>0</u>		<u>74</u>			
10 min	<u>0</u>		<u>74</u>			
15 min	<u>0</u>		<u>74</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Puff When opened then nothing

By Tom JF

Witness _____

(Position)

E-mail address _____