



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

SEP 13 2016

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 9-13-16 Operator Slide Energy API #30-0 43-20 855

Property Name San Isidro Well No. 11-14 Location: Unit 11 Section 11 Township 20 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate      Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>30</u>		
10 min	<u>0</u>		<u>30</u>		
15 min	<u>0</u>		<u>30</u>		
20 min					
25 min					
30 min					

**FLOW CHARACTERISTICS**  
BRADENHEAD INTERMEDIATE

Steady Flow     

Surges     

Down to Nothing   /  

Nothing     

Gas     

Gas & Water     

Water     

   bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE     

REMARKS:

light blow to dead at 3 seconds - nothing  
when opened after 5 min shut in

Johnny Boyer  
(Position)

Witness

Monica Cochran

mail address