NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-18-16 Operator ConocoPhillips API #30-0 39-07448

Property Name SJ 28-7 Ut Well No. 74 Location: Unit ___ Section 11 Township 28 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 93 Intermediate 0 Casing 93 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	Int	Csg	INTERM Int	Csg	FLOW CHARACTERISTICS BRADENHEAD	INTERMEDIATE
TIME 5 min	0	0	94	0	94	Vapors Steady Flow	✓ Vapors.
10 min	0	0	94	0	94	Vapors Surges	
15 min	0	0	94	0	94	Vapors Down to Nothing	
20 min				0	94	Vapors Nothing ✓	
25 min				0	94	Vapors Gas	
30 min				0	94	Vapors. Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR____ FRESH____ SALTY____ SULFUR____ BLACK____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: BH - Have worked on wellhead. Nothing when opened - puff when opened after 5 min shut in - int light blow to vapors at 1 min vapors rest of 30 min test. Nothing sound when opened - vapors.

By Lawrence Lucero Witness Monica Kuehling

(Position)

E-mail address _____