

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Tony Delfin
Acting Cabinet Secretary

David R. Catanach, Division Director
Oil Conservation Division



October 24, 2016

ConocoPhillips Company
Attn: Lori Notor
3401 E. 30th Street
Farmington, NM 87402

Re: Bradenhead Test Failure

Well: Jicarilla 20 #5, UL P, Sec 20, Tw 25N, Rge 4W, API # 30-039-20446

Certified Mail Return Receipt: 7015 0640 0007 1331 3667

Dear Ms. Notor:

The 2016 Bradenhead test on the above well indicates a failure. To comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before **December 20, 2016**. Initial Surface Casing psi was 131. Initial Production Casing psi was 150. Production casing did not drop. However, gas analysis shows the same gas on surface casing and production casing

Reference: RBDMS MPK1623238673 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 116.

Sincerely-yours,

Brandon Powell
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File