

State of New Mexico  
Energy, Minerals and Natural Resources Department

---

Susana Martinez  
Governor

Tony Delfin  
Acting Cabinet Secretary

David R. Catanach, Division Director  
Oil Conservation Division



October 24, 2016

ConocoPhillips Company  
Attn: Lori Notor  
3401 E. 30<sup>th</sup> Street  
Farmington, NM 87402

**Re:** Bradenhead Test Failure  
**Well:** San Juan 28 6 Unit #169, UL M, Sec 2, Tw 27N, Rge 6W, API # 30-039-20477

**Certified Mail Return Receipt: 7015 0640 0007 1331 3667**

Dear Ms. Notor:

The 2016 Bradenhead test on the above well indicates a failure. To comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before **December 20, 2016**. Initial Surface Casing psi was 0. Initial Intermediate Casing psi was 247. Initial Production Casing psi was 247. Production Casing dropped while Intermediate Casing was open indicating direct communication.

The Gas analysis and wellbore schematic have been received.

Reference: RBDMS MPK1622540260 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 116.

Sincerely yours,

Brandon Powell  
Deputy Oil and Gas Inspector  
District III - Aztec

CC: Well File