



**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://enmwd.state.nm.us/ocd/District III/district.htm](http://enmwd.state.nm.us/ocd/District%20III/district.htm)**

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 03 2016

Date of Test 11/3/2016 Operator Burlington API #30-039-07164

Property Name San Juan 27-51 Well No. 25 Location: Unit Section 3 Township 27 Range 5

Well Status (Shut-In or Producing) Initial PSI: Tubing 125.2 Intermediate 66.3 Casing 127.5 Bradenhead 1.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME 5 min	TSTM	66.4	128.5	5.5	129.2
10 min	TSTM	66.6	128.4	0.1	129.3
15 min	TSTM	66.6	128.6	TSTM	129.3
20 min	TSTM	67.0	128.9	TSTM	129.3
25 min	TSTM	67.2	129.1	TSTM	129.4
30 min	TSTM	67.2	129.1	TSTM	129.5

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas	X	X
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0.6

INTERMEDIATE 0.9

REMARKS:

REMARKS: BH through 1" fitting, blew down to ^{vapor} ~~nothing~~ in 4 sec, vapor for rest of test. Int through 1" fitting, hard blow for 6 min, moderate to light blow for 2 min, down to whisper by 8 min 30 sec down to breath in 20 min. Request gas analysis all strings

By David W. Osh

Witness Jonathan D. Kell

(Position)

E-mail address _____