



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 11-4-16 Operator BRAmerica API # 30-0 45-28553

Property Name Crebu Middle Mesa SW Well # 2 Location: Unit M Sec 11 Twn 3 (Rge 7)

Land Type:

State _____
Federal ✓
Private _____
Indian _____

OIL CONS. DIV DIST. 3

NOV 04 2016

Well Type:

Water Injection _____
Salt Water Disposal ✓
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N) (N) TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 433
Int. Casing Pres. 0

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. 2500

Pressured annulus up to 560 psi. for 30 mins. Test passed/failed (passed)

REMARKS:

Pressured to 560 dropped to 558 & held

Kill test performed on #3 pump 1 & 2 need to be tested when fixed

By Par Miller
(Operator Representative)

Witness Monica Cuckling
(NMOCD)

HS
(Position)

Revised 02-11-02