



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

NOV 10 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-10-16 Operator XTO Energy API #30-0 45-09214
Property Name Stedje Gas Com Well No. 1 Location: Unit 1 Section 27 Township 30 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 143 Intermediate N/A Casing 143 Bradenhead 72

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
<u>5 min</u>	<u>0</u>		<u>141</u>		
<u>10 min</u>	<u>0</u>		<u>148</u>		
<u>15 min</u>	<u>0</u>		<u>147</u>		
<u>20 min</u>	<u>0</u>		<u>148</u>		
<u>25 min</u>	<u>0</u>		<u>149</u>		
<u>30 min</u>	<u>0</u>		<u>150</u>		

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow ✓ James
Surges _____
Down to Nothing _____
Nothing _____
Gas ✓ _____
Gas & Water _____
Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 8

INTERMEDIATE N/A

REMARKS:

med blow to James for full 30 min test

By Ken Durham

Witness Monica Kuchling

Prod Foreman
(Position)

E-mail address Ken-Durham@xtoenergy.com

Gas analysis from BH
& casing and also analysis
from fruitland #3 on location