

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		7. If Unit of CA/Agreement, Name and/or No. San Juan 28-5 Unit
2. Name of Operator Burlington Resources Oil & Gas Company LP		8. Well Name and No. San Juan 28-5 Unit 72
3a. Address PO Box 4289, Farmington, NM 87499	3b. Phone No. (include area code) (505) 326-9700	9. API Well No. 30-039-20028
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Surface Unit N (SESW), 1600' FSL & 1500' FWL, Sec. 35, T28N, R5W		10. Field and Pool or Exploratory Area Basin Dakota
		11. Country or Parish, State Rio Arriba, New Mexico

RECEIVED
APR 27 2015

Farmington Field Office
Bureau of Land Management

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input checked="" type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	P&A Corrective
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	Reclamation

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The subject well was P&A'd on 9/7/10 and Burlington Resources completed the final reclamation on 9/14/12 w/seeding completed on 10/9/12.

Following an inspection by Burlington Resources, the location was disc'd and reseeded on 3/27/15. Non-native gravel on location was also removed.

OIL CONS. DIV DIST. 3

APPROVED

DEC 05 2016

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Dollie L. Busse		Title Staff Regulatory Technician
Signature <i>Dollie L. Busse</i>		Date <i>4/24/15</i>

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by <i>[Signature]</i>	Title <i>ARM</i>	Date <i>11/22/16</i>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office <i>BLM</i>	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Corrective

Reclamation Form:

Date: 3/27/15

Well Name: SAN JUAN 28-5 #72

Footages: 1600' FSL + 1500' FWL Unit Letter: N

Section: 35, T-28-N, R-5-W, County: DOLORES ARIZONA State: NM

Reclamation Contractor: N/A

Reclamation Start Date: N/A

Reclamation Complete Date: N/A

Road Completion Date: N/A

Seeding Date: 3/27/15 - NRE

**PIT MARKER STATUS (When Required): Picture of Marker set needed

MARKER PLACED: N/A (DATE)

LATITUDE: N/A

LONGITUDE: N/A

Pit Manifold removed N/A (DATE)

Construction Inspector: JARED CHAVEZ Date: 3/30/15

Inspector Signature: [Signature]

Office Use Only: Subtask DSM Folder Pictures

Re-Contour Location Plan

Well Name: SJ 28-5 #72


Drafted by COP Rep: JARED CHAVEZ

Approved by BLM FFO Rep:



Date: 10/14/14

Site Diagram: Corrective Reclamation



Re-Contour Details:



GET RID OF GRAVEL, DISC + RESEED LOCATION ≈ \$6000.00 - INCLUDES ONSITE

2 DAYS