



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

DEC 02 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-2-16 Operator B America API #30-0 45-27341
Property Name Veblen Middleman SWD Well No. 1 Location: Unit 32 Township 31 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 217 Intermediate 0 Casing 5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	-5	0	-5
10 min	0	0	-5	0	-5
15 min	0	0	-5	0	-5
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: BH. Nothing when opened. Nothing when
opened after 5 min. Int. light blow to head vapors
at 5 seconds. Nothing when opened after 5 min.

By Jake Plana

Witness Monica Cushing

(Position)

E-mail address _____