



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT
(TA OR UIC)

Date of Test 6-DEC-2016 Operator BURLINGTON API # 30-0 39-20477

Property Name SAN JUAN 28-6 Well # 169 Location: Unit M Sec 2 Twn 27 Rge 4

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒ _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 515
Bradenhead Pres. 0
Tubing Pres. _____
Int. Casing Pres. _____

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 595 psi. for 18 mins. Test passed/failed

REMARKS: RETRIEVABLE BRIDGE PLUG WAS SET 7434

1000 PSI SPRING, 40 MINUTE CLOCK. THE ANNULUS WAS
PRESSURED UP TO 595 PSI AND PRESSURE FELL TO 575 AND
HELD FOR THE LAST 18 MINUTES.

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

CA REP
(Position)

OIL CONS. DIV DIST. 3

Revised 02-11-02

DEC 05 2016