

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company WPX Energy Production	Contact Deborah Watson	
Address PO Box 640	Telephone No. 505-333-1880/505-386-9693	
Facility Name Rosa Unit #640H	Facility Type Well Site	
Surface Owner Federal	Mineral Owner Federal	API No. 30-039-31313

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	19	31N	05W	963	North	512	West	Rio Arriba

Latitude N36.889685 Longitude W107.406029

**NATURE OF RELEASE**

Type of Release natural gas	Volume of Release 564 mcf	Volume Recovered 0 mcf
Source of Release Wellhead/equipment failure	Date and Hour of Occurrence 1/9/17 04:30	Date and Hour of Discovery 1/9/17 07:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Whitney Thomas (BLM-FFO) Vanessa Fields (NMOCD) Additional NMOCD and BLM-FFO representatives were contacted prior to 10:30AM	
By Whom? N/A	Date and Hour 1/9/17 ≈ 10:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Wellhead developed leak on the inlet of the casing valve. The well was controlled and wellhead replaced.

Describe Area Affected and Cleanup Action Taken.\*

- The well vented 564 mcf natural gas.
- Well was controlled and wellhead replaced.
- The well was returned to production on January 11, 2017.
- No cleanup required.

OIL CONS. DIV DIST. 3  
JAN 23 2017

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Deborah Watson</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Deborah Watson	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: 1/24/2017	Expiration Date:
E-mail Address: deborah.watson@wpxenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/23/2017	Phone: 505-333-1880	<i>NVE 1701132188</i>

\* Attach Additional Sheets If Necessary

①