

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 4/15/2016 Operator Encana API #30-0 39-21046  
 Property Name Dunn Well No. 2 Location: Unit F Section 10 Township 23N Range 7W  
 Pressure (Shut-In or Producing) Producing Tubing 22 Intermediate n/a Casing 22 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	0		22	Steady Flow		
10 minutes	0		22	Surges		
15 minutes	0		22	Down to Nothing		
20 minutes				Nothing		
25 minutes				Gas		
30 minutes				Gas & Water		
				Water		

ON CONS. DIV DIST. 3  
NOV 14 2016

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_  
 5 MINUTE SHUT-IN \_\_\_\_\_ BRADENHEAD\_ 0 \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

By Michael Veazey Witness \_\_\_\_\_  
Lease Operator  
 (Position)

**\*\*\*FAILURE TO COMPLY  
WITH BRADENHEAD TEST  
MEMORANDUM DATED  
FEBRUARY 1, 2016**