



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnrd.state.nm.us/ocd/District III/3district.htm>

OIL CONS. DIV DIST. 3  
DEC 09 2016

**BRADENHEAD TEST REPORT**  
(submit 1 copy to above address)

Date of Test 9-28-16 Operator: Enervest Operating, LLC API # 30-039-22292

Property Name: Jicarilla A Well No. 4E Location: Unit: D Section: 19 Township: 26N Range: 5W

Well Status (Shut-In or Producing) Initial PSI: Tubing 132 Intermediate — Casing 34 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	1	136		
10 min	0	1	138		
15 min	0	1	141		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR  FRESH  SALTY  SULFUR  BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:  
\_\_\_\_\_  
\_\_\_\_\_

By Willie J. Freeman  
Prod. Foreman  
(Position)

Witness \_\_\_\_\_

**\*\*\*FAILURE TO COMPLY  
WITH BRADENHEAD TEST  
MEMORANDUM DATED  
FEBRUARY 1, 2016**

E-mail address \_\_\_\_\_