

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

OL COMB. DIV DIST. 6 DEC 6 9 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

| Date of TestOperator: | Enervest Operating, LLC API #30-039-29771 |
|---|---|
| Property Name: <u>Jic. Apache 102</u> Well No. <u>9M</u> Location: Unit: <u>O</u> Section: <u>4</u> Township: <u>26N</u> Range: <u>4W</u> | |
| Well Status(Shut-In or Producing) Initial PSI: Tubing 136 Intermediate Casing 140 Bradenhead | |
| OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH | |
| PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg | FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE |
| TIME 5 min 6 140 | Steady Flow |
| 10 min 6 142 | Surges |
| 15 min U 145 | Down to Nothing |
| 20 min | Nothing × |
| 25 min | Gas |
| 30 min | Gas & Water |
| | Water |
| If bradenhead flowed water, check all of the descriptions that apply below: | |
| CLEAR FRESH SALTY | SULFURBLACK |
| 5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE | |
| REMARKS: Slight puff | |
| | |
| | TO COMPLET |
| By w | itness***FAILURE TO COMPLY ****FAILURE TO COMPLY |
| By Witness | |
| E-mail address | |