

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

011 CONS. DIV DIST. 3 DEC 0 9 2313 OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test S-3-16 Operator: Enervest Operating, LLC API #30-039-23252					
Property Name: <u>Jicarilla Cont. 147</u> Well No. <u>5E</u> Location: Unit: <u>D</u> Section: <u>7</u> Township: <u>25N</u> Range: <u>5W</u>					
Well Status(Shut-In or Producing) Initial PSI: Tubing 105 Intermediate Casing 110 Bradenhead _ 5					
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
0	PRESSURE Bradenhead INTERM BH Int Csg Int Csg				FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min		111	IIIC		Steady Flow
10 min 💍		115			Surges
15 min (117			Down to Nothing
20 min_					Nothing
25 min					Gas
30 min					Gas & Water
					Water
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR	R	FRESH	\$	SALTY	SULFUR BLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD D INTERMEDIATE					
REMARKS: Blew down in 25ec					
COMPLY					
By Witness Witness ***FAILURE TO COMPLY ***FAILURE TO COMPLY ****FAILURE TO COMPLY ****FAILURE TO COMPLY ****FAILURE TO COMPLY *****FAILURE TO COMPLY *****************************					
Witness					
(Position) ***********************************					