

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

CLC 13. ENDIST. 3

DEC 0 9 2015

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 9-15-16 Operator	Enervest Operating, LLC API #30-039-27783
Property Name:Jicarilla CWell No. 1C _Location: Unit: _G _Section: _11 _Township: _26N _Range: 4W	
Well Status(Shut-In or Producing) Initial PSI: Tubing 35 Intermediate Casing 110 Bradenhead 6	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min () ((1)	Steady Flow
10 min 0 113	Surges
15 min () (16	Down to Nothing
20 min	Nothing \( \square \)
25 min	Gas
30 min	Gas & Water
Water	
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE	
REMARKS:	
By Wille Ve	WitnessTO COMPLITE
By Wille II V	EATLURE THEADTED
(Position)	****FAILURE TO COMPLY  ***FAILURE TO COMPLY  ***FAILURE TO COMPLY  ***FAILURE TO COMPLY  ***FAILURE TO COMPLY  ****FAILURE TO COMPLY  *****FAILURE TO COMPLY  ***********************************
E-mail address	MEMBRUAI