



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-1-14 Operator Four Star O&G API #30-0 45-06545
Property Name Phu Charbs Well No. 6 Location: Unit 13 Township 27 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 70 Intermediate N/A Casing 76 Bradenhead 22

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	2		76		
10 min	2		76		
15 min	2		74		
20 min	2		67		
25 min	2		63		
30 min	2		61		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓ Water</u>	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water <u>✓</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH ✓ SALTY ✓ SULFUR ✓ BLACK ✓

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 22

INTERMEDIATE N/A

REMARKS:

Black to clear water from start
Well started flowing at 17 min.

4 Gallons = 4 min + 4 at 10 min + 3.5 at 15 min + 1.5 at 16 min

By Randy Calote

Witness

Monica Lueking
+ 4 at 22 min. Water Sample taken
+ 4 at 28 min
+ 1.5 at 30 min.
21.5 gallons in 30 min

caldor service
(Position)

E-mail address Randy@caldor-service.com