



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

CDL COND. DIV DIST. 3

DEC 09 2015

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 10-21-16 Operator: Enervest Operating, LLC API # 30-039-06896

Property Name: Champlin Well No. 05 Location: Unit: K Section: 25 Township: 27N Range: 4W

Well Status(Shut-In or Producing) Initial PSI: Tubing 100 Intermediate - Casing 100 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	100		
10 min	0	1	102		
15 min	0	1	105		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

Slight blow / 10 sec.

By Wally Per  
Prod. Foreman  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_

**\*\*\*\*FAILURE TO COMPLY  
WITH BRADENHEAD TEST  
MEMORANDUM DATED  
FEBRUARY 1, 2016**