



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

FEB 08 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-7-17 Operator Chuck Rogers API #30-0 45-85-126

Property Name Mar Vista Well No. 1 Location: Unit Section Township Range

Well Status (Shut-In) or Producing) Initial PSI: Tubing 783 Intermediate 0 Casing -8 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	0	0	-8	0	-6
10 min	0	0	-8	0	-6
15 min	0	0	-8	0	-6
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	1
Nothing	
Gas	1
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0 5 min

REMARKS:

B-H Dead At 2 seconds B-H nothing After 5 minutes
Intermittent

nothing After 5 minutes

By MSO
(Position)

Witness Monica Kuchling

E-mail address