



(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/oed/District III/3ddistrict.htm](http://emnrd.state.nm.us/oed/District%20III/3ddistrict.htm)

OIL CONS. DIV DIST. 3

FEB 23 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-23-17 Operator Burlington API #30-0 45-32833

Property Name LC Kelly Con Well No. 1005 Location: Unit Section 4 Township 30 Range 12

Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME	0		0		
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

REMARKS: Nothing when opened - nothing after
5 min shutter

By V. A. MONTVOYA
WELLSITE SUPERVISOR
(Position)

Witness

E-mail address