



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

MAR 08 2017

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 3/8/2017 Operator Burlington API # 30-0 39-27333

Property Name San Juan 29-7 Unit Well # 190 Location: Unit 16 Sec 29 Rge 7

Land Type:

State X
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. NA
Int. Casing Pres. NA

Tbg. SI Pres. NA
Tbg. Inj. Pres. NA

Max. Inj. Pres. NA

P1 ired annulus up to 620 psi. for 30 mins. Test passed/failed

REMARKS: MET for Casing Repair. 1000lbs spring, 1 hr clock, 1000lbs/hr chart, pressured up to 620 psi from 0 psi, 5min 615 psi Bt O psi, 10 min 608 psi Bt O psi, 15 min 608 psi Bt O psi, 20 min 605 psi Bt O psi, 25 min 602 psi Bt O psi, 30 min 600 psi Bt O psi, bled back to 0 psi

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02