



**NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 9/19/16 Operator Merrion Oil Gas Corporation API # 3003906354

Property Name North Lindrith 1 (MV/PC) Location: Unit M Section 20 Township 26N Range 02W  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 25 Intermediate \_\_\_\_\_ Casing 30 Bradenhead 0

**OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH**

Time	Bradenhead			Intermediate		Flowed	Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	30				Steady Flow	
10 minutes	0	30				Surges	
15 minutes	0	30				Down to Nothing	
20 minutes	0	30				No Flow	✓
25 minutes	0	30				Gas	
30 minutes	0	30				Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate \_\_\_\_\_

**OIL CONS. DIV DIST. 3**  
**FEB 24 2017**

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**\*\*\*\*FAILURE TO COMPLY  
WITH BRADENHEAD TEST  
MEMORANDUM DATED  
FEBRUARY 1, 2016**

By Kyle Davis Witness \_\_\_\_\_  
Pumper  
(Position)

*PHD*  
*10/16*