



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4.12.17 Operator Burlington Res API #30-0 45-08438
Property Name Vandewater Well No. 1 Location: Unit Section 12 Township 29 Range 8
Well Status(Shut-In or Producing) Initial PSI: Tubing 43 Intermediate 42 Casing 44 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	42	44	0	45
10 min	0	43	44	0	45
15 min	0	43	45	0	46
20 min				0	46
25 min				0	46
30 min				0	46

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	☒
Surges	☐
Down to Nothing	☐
Nothing	☒
Gas	☒
Gas & Water	☐
Water	☐

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 2

REMARKS:

BH Nothing when opened. - Nothing
when opened after 5 min shut-in - Tub. Pres (blow)
when opened - to light blow at 1.1 min - light blow at 5 for

By William J. Shoss Witness Monica Cuckling

(Position)

E-mail address

Rest of 30 min test.
Gas analysis Int & prod.