



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III3distric.htm>

OIL CONS. DIV DIST. 3

APR 20 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-20-2017 Operator Thompson Eng. API # 30-043-20337

Property Name Federal B Well No. 5 Location: Unit D Section 34 Township 23 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 20 Intermediate 0 Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	20	0	20
10 min	0	0	20	0	20
15 min	0	0	20	0	20
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	X
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 psi INTERMEDIATE 0 psi

REMARKS:

Intermediate has cement behind ball plugs. Nothing on BH when opened.
Nothing on BH after 5 minute shut in. Nothing on intermediate
when opened. Nothing on intermediate after 5 min shut in.

By Michael L Dean

MICHAEL L DEAN

(Position)

Witness Thomas K. Clements NMOC

E-mail address _____