

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

| | |
|---|---------------------------------|
| Name of Company: BP | Contact: Steve Moskal |
| Address: 200 Energy Court, Farmington, NM 87401 | Telephone No.: 505-326-9497 |
| Facility Name: MOORE B No. 004A | Facility Type: Natural gas well |
| Surface Owner: Federal | Mineral Owner: Federal |
| API No. 3004522273 | |

LOCATION OF RELEASE

| | | | | | | | | |
|------------------|--------------|-----------------|--------------|----------------------|---------------------------|----------------------|------------------------|------------------|
| Unit Letter P | Section 5 | Township 30N | Range 08W | Feet from the 960 | North/South Line South | Feet from the 850 | East/West Line East | County: San Juan |
|------------------|--------------|-----------------|--------------|----------------------|---------------------------|----------------------|------------------------|------------------|

Latitude 36.83549° Longitude -107.69293°

NATURE OF RELEASE


| | | |
|--|--|---|
| Type of Release: natural gas | Volume of Release: 58.6 mcf | Volume Recovered: none |
| Source of Release: Scrubber dump | Date and Hour of Occurrence: 4/2/17; 8:30AM | Date and Hour of Discovery: 4/3/17; 11:00 AM |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour: | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* 1/4" tubing line on fuel gas broke allowing release. No action necessary as gas was vented to atmosphere.

Describe Area Affected and Cleanup Action Taken.* Tubing vented directly atmosphere. No action necessary. Valve and tubing will be replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|---|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Steve Moskal | Approved by Environmental Specialist:  | |
| Title: Field Environmental Coordinator | Approval Date: 4/24/2017 | Expiration Date: |
| E-mail Address: steven.moskal@bp.com | Conditions of Approval: NMF1711438660 | Attached <input type="checkbox"/> |
| Date: April 14, 2017 | Phone: 505-326-9497 | |

* Attach Additional Sheets If Necessary

OIL CONS. DIV DIST. 3
APR 21 2017