



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3district.htm](http://emnr.state.nm.us/ocd/District%20III3district.htm)

OIL CONS. DIV DIST. 3

APR 21 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/21/2017 Operator Thompson Eng. API #30-0 45-28588
Property Name Vanderwart A Well No. 15 Location: Unit Section 24 Township 29 Range 8
Well Status (~~Shut In~~ or Producing) Initial PSI: Tubing 82 Intermediate NA Casing 83 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	NA	83		
10 min	0		83		
15 min	0		83		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

Nothing on BH when opened. Nothing after 5 minute shut in.

By Scott Rodgers SCOTT RODGERS
LEASE OPERATOR
(Position)

Witness Thompson Eng. MOCO

E-mail address