



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnr.state.nm.us/ocd/District/III3district.htm>

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 23-MAY-2017 Operator DOM WIDON API #30-0 31-20362

Property Name SOUTH HISPANI Well No. 48 Location: Unit 6 Section 12 Township 17 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	N/A	0		
10 min	0	1	0		
15 min	0	1	0		
20 min				N/A	
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	NA
Gas		
Gas & Water		
Water		✓

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT

By Ralph Williams Jr.  
Field Supervisor  
(Position)

Witness John Durbin

E-mail address \_\_\_\_\_

OIL CONS. DIV DIST. 3  
MAY 23 2017