



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.state.nm.us/ocd/District/III/3distric.htm>
OIL CONS. DIV DIST. 3

MAY 15 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-15-2017 Operator Southland Royalty API #30-0 45-11434

Property Name San Juan 32-5 Well No. 18 Location: Unit B Section 16 Township 32 Range 6

Well Status (~~Shut-in~~ or Producing) Initial PSI: Tubing 65 Intermediate 30 Casing 82 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	30	84	0	84
10 min	0	30	84	0	84
15 min	0	29	84	0	84
20 min	0	29	84	0	84
25 min	0	29	84	0	84
30 min	0	29	84	0	84

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	X
Nothing		
Gas	X	X
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 psi INTERMEDIATE 1 psi

REMARKS:

Puff to nothing on Btl when opened. In five seconds. Nothing on BH
after five minute shut-in. Hard puff to nothing in two seconds on intermediate
when opened. One psi on intermediate after five minute shut in with a slight puff.
No water or intermedate, a little moisture in elbow and behind bushing.

By Jonathan Hardy

Witness John K. De Niro

Lease Operator
(Position)

E-mail address _____