

OIL CONS. DIV DIST. 3
MAY 12 2017

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test April 27, 2017 Operator San Juan Resources API #30-0 45-29139
Property Name Flora Vista 19 Well No. 2 Location: Unit N Section 19 Township 30N Range 11W
Pressure (Shut-In or Producing) Producing Tubing 3 Intermediate N/A Casing 4 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURES:

TESTING TIME	BRADENHEAD			INTERMEDIATE	
	BH	INT	CSG	INT	CSG
5 minutes	0	N/A	4	N/A	N/A
10 minutes	0		4		
15 minutes	0		4		
20 minutes					
25 minutes					
30 minutes					

	BRADENHEAD	INTERMEDIATE
	FLOWED	FLOWED
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN _____ BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Nothing on BradenHead

By Justin Stone Witness _____
Lease Operator
(Position)