

MAY 12 2017

(505) 334-6178 FAX: (505) 334-6170
<http://nemr.state.nm.us/ocd/DistrictIII/3distric.htm>

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test April 27, 2017 Operator San Juan Resources API #30-0 45-31908
Property Name Cecil Cast Well No. 2A Location: Unit E Section 19 Township 30N Range 11W
Pressure (Shut-In or Producing) Producing Tubing 14 Intermediate N/A Casing 16 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURES:

TESTING TIME	BRADENHEAD			INTERMEDIATE	
	BH	INT	CSG	INT	CSG
5 minutes	0	N/A	16	N/A	N/A
10 minutes	0		16		
15 minutes	0		16		
20 minutes					
25 minutes					
30 minutes					

BRADENHEAD INTERMEDIATE

	FLOWED	FLOWED
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Nothing on Bradenhead

By Justin Stone Witness _____
Lease Operator
(Position)