



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

MECHANICAL INTEGRITY TEST REPORT

JUN 06 2017

(TA OR UIC)

Date of Test 6/6/2017 Operator Burlington API # 30-0 45-26278

Property Name Huerfano Unit Well # 11DE Location: Unit 3H Sec 3 Twn 26 Rge 10

Land Type:

State _____
Federal X _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 0
Mudhead Pres. 0
Tubing Pres. NA
Int. Casing Pres. NA

Tbg. SI Pres. NA
Tbg. Inj. Pres. NA

Max. Inj. Pres. NA

Pressured annulus up to 570 psi. for 35 mins. Test passed/failed

REMARKS: 1000 lbs spring, 1 hr clock, last calibration 5/26/2017, on a 1hr 1000 lbs chart,
Start @ 0 psi, pressured up to 570 psi, 5 min 572 psi BH 0 psi, 10 min 572 psi
BH 0 psi, 15 min 572 psi BH 0 psi, 20 min 569 psi BH 0 psi, 25 min 565 psi
BH 0 psi, 30 min 563 psi BH 0 psi, 35 min 563 psi BH 0 psi, bled back
down to 0 psi

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

[Signature]
(Position)

Revised 02-11-02