



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST.

JUN 06 2011

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-6-11 Operator Dommon API #30-0 31-05223

Property Name Hsu Well No. 34 Location: Unit I Section 36 Township 18 Range 9

Well Status(Shut-In or Producing) Initial PSI: Tubing _____ Intermediate _____ Casing _____ Bradenhead _____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS: Concrete slab- no bradenhead.

By [Signature]

(Position)

Witness [Signature]

E-mail address _____