



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

30-039-23503

Date of Test 5-11-17 Operator THOMPSON API # 30-039-23503  
Property Name Lybrook 7-27 #2 Location: Unit 1 Section 27 Township 24N Range 9W  
(Well Name and Number) 27 24N  
Pressure (Shut-in or Producing) 0 Tubing BB Intermediate      Casing 109 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>109</u>					
10 minutes	<u>0</u>	<u>109</u>					
15 minutes	<u>0</u>	<u>109</u>					
20 minutes							
25 minutes							
30 minutes							
5 minute SI	<u>0</u>	<u>109</u>					

Steady Flow		
Surges		
Down to Nothing		
No Flow	<u>X</u>	<u>✓</u>
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear      Fresh      Salty      Sulfur      Black     

5 Minute Shut-in Bradenhead 0 Intermediate     

REMARKS:

By Mike Wagoner

Witness     

(Position)

NMOCD Test Area:

1