

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 5-10-17			,	Operator_	THOMPSO	∠ AP	T#30-0 <u>39 - 242/8</u>		
Property Name Down Well No. 15 Location: Unit M Section 9 Township 23N Range 7W									
Well Status(Shut-In or Producing) Initial PSI: Tubing 75 Intermediate Casing 95 Bradenhead 0									
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH									
Testing	BH Int Csg Int Csg					FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE			
TIME 5 min_	0		95			Steady Flow		OIL CONS. DIV DIST. 3	
10 min_	0		95			Surges		JUN 0 5 2017	
15 min_	0		95			Down to Not	Down to Nothing		
20 min_						Nothing	~		
25 min_						Gas			
30 min_						Gas & Water	·		
						Water			
If bradenhead flowed water, check all of the descriptions that apply below:									
CLEAR FRESH SALTY SULFUR BLACK									
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE REMARKS:									
By MICHAGE L DEAN Witness									
E-mail address MICHAGE, DEAN Ca WALSHENG, NET									