



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO DRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 27-JUNE-2017 Operator THOMPSON API #30-0 39-23406

Property Name ESRIDGALP Well No. 27 Location: Unit _____ Section 19 Township 24 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 2 Intermediate N/A Casing 183 Bradenhead 64

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME	0	N/A	183		
5 min	0		183		
10 min	0		183		
15 min	0		183		
20 min	0		183		
25 min	0		183		
30 min	0		183		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing	X	
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 40

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT
BLEW DOWN TO NOTHING IN 1 SECOND
REQUESTED A GAS ANALYSIS

By

John Thompson
Well Operator
(Position)

Witness

John Thompson

OIL CONS. DIV DIST. 3

JUN 27 2017

E-mail address _____