

NEW MEXICO ENERGY, MUNERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVIGION
AZTEC DISTRICT OFFICE
1000 RIO DRAZOS HOAD
AZTEC NM 17410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3 distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 28 -)(1) Operator (0) API #30-0 39 - 30644
Property Name San Juan 30-5 Well No. 72M Location: Unit P Section Township 30 Range 5
Well Status(Shut-In or Producing) Initial PSI: Tubing 1/2 Intermediate Casing Bradenhead O
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg TIME
5 min 600 Steady Flow
10 min 0 0 000 Surges
15 min 0 000 590 Down to Nothing
20 min Nothing
25 min Gas_
30 min Gas & Water
Water
If bradenhead flowed water, check all of the descriptions that apply below:
CLEAR FRESH SALTY SULFUR BLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD Q INTERMEDIATE O
REMARKS: OPENED THE BARGEMEND AND NOTHING CAME OUT
OPENED THE INTERMEDIATE AND NOTHING CANEOUT
By Soll CONS. DIV DIST. 3
(Position) 011 0011 9 2017
E-mail address
A TARMA WALLOWS